

# Auto Credit Center

✔ Get Approved    ✔ Get Driving

## 2012 SCION XB

Stock #: 22666

Transmission: AUTOMATIC

VIN #: JTLZE4FE9CJ000858

ENGINE: , I4

INTERIOR: GRAY


DRIVE TRAIN: Front-wheel drive

COLOR: WHITE

MILEAGE: 127827



**Tier 2**  
Scan for Pricing and  
Payment Details



**SALES HOURS**  
**Mon-Fri 9am-6pm**  
**Sat- 9am-5pm**

**Dealer Contact Info**  
Phone - 727-222-5501  
Info@autocreditcenterfl.com

- » ABS Brakes
- » Air Conditioning
- » Alloy Wheels
- » AM/FM Radio
- » Cargo Net
- » CD Changer
- » CD Player
- » Child Safety Door Locks
- » Chrome Wheels
- » Deep Tinted Glass
- » Driver Airbag
- » Electrochromic Exterior Rearview Mirror
- » First Aid Kit
- » Fog Lights
- » Front Side Airbag
- » Front Side Airbag with Head Protection
- » Full Size Spare Tire
- » Genuine Wood Trim
- » Interval Wipers
- » Leather Seat
- » Leather Steering Wheel
- » Navigation Aid
- » Passenger Airbag
- » Power Door Locks
- » Power Trunk Lid
- » Power Windows
- » Rear Spoiler
- » Rear Window Defogger
- » Rear Wiper
- » Remote Ignition
- » Run Flat Tires
- » Sliding Rear Pickup Truck Window
- » Steel Wheels
- » Steering Wheel Mounted Controls
- » Tachometer
- » Telescopic Steering Column
- » Tilt Steering Column
- » Tire Pressure Monitor
- » Traction Control
- » Trip Computer
- » Vehicle Stability Control System

**Price Disclaimer** - The total sales price is **\$9990.00**. The displayed price is the total sales price not including a **\$495** doc fee, state and local tax, registration fees, interest, or optional products such as GAP insurance or a vehicle service contract. Please see dealer for personalized financing terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Auto Credit Center.

This Page is intentionally left blank



**Below is a list of some major defects that may occur in motor vehicles.**

**Frame & Body**

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

**Engine**

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

**Transmission & Drive Shaft**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

**Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

**Cooling System**

- Leakage including radiator
- Improperly functioning water pump

**Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

**Fuel System**

- Visible leakage

**Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

**Brake System**

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

**Steering System**

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

**Suspension System**

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

**Tires**

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

**Wheels**

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

**Exhaust System**

- Leakage
- Catalytic Converters

**Airbags**

*AUTO CREDIT CENTER*

DEALER

*8201 US HWY 19 PORT RICHEY FLORIDA 34668*

ADDRESS

*Chris Maher(727-222-5501)*

*Email: Chrisjr@autocreditcenterfl.com*

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)