

# Auto Credit Center

✔ Get Approved    ✔ Get Driving

## 2006 LEXUS RX 330

Stock #: 22594

Transmission: AUTOMATIC

VIN #: 2T2GA31U36C049542

ENGINE: , V6

INTERIOR: GRAY

DRIVE TRAIN: Front-wheel drive

COLOR: BLUE

MILEAGE: 110652



**Tier 2**  
Scan for Pricing and  
Payment Details



**SALES HOURS**  
Mon-Fri 9am-6pm  
Sat- 9am-5pm

**Dealer Contact Info**  
Phone - 727-222-5501  
Info@autocreditcenterfl.com

- » Front mounted engine
- » Premium Unleaded
- » Spark ignition system
- » Variable intake manifold
- » Transverse mounted engine
- » Aluminum engine block
- » Aluminum cylinder head
- » Heavy-duty alternator
- » Lead acid battery
- » Heavy-duty radiator
- » Electronic stability control system
- » 4-wheel disc brakes
- » 4-wheel antilock (ABS) brakes
- » Brake assist system
- » Projector beam headlights
- » High-intensity discharge low beam headlights
- » Front headlight washers
- » Auto on/off headlight control
- » Daytime running lights
- » Multiple enclosed headlights
- » ULEV II emissions
- » Tier 2 Bin 5 emissions
- » Rear lip spoiler
- » Fully galvanized steel body panels with side impact beams
- » 4 doors
- » Body-colored front bumper
- » Body-colored rear bumper
- » Body-colored bodyside moldings
- » Chrome grille
- » Black side window trim
- » Body-colored door handles
- » Metallic paint
- » Conventional left rear passenger door
- » Power door mirrors
- » Power liftgate rear cargo door
- » Heated driver and passenger side door mirrors
- » Conventional right rear passenger door
- » Driver visor with expandable coverage
- » Driver visor mirror
- » Illuminated driver visor mirror
- » Passenger visor with expandable coverage
- » Passenger visor mirror
- » Bucket front seats
- » Heated driver and front passenger seats
- » Driver seat with 8-way directional controls
- » Driver seat with 2-way power lumbar
- » Front passenger seat with 8-way directional controls
- » Front passenger seat with 2-way power lumbar
- » Height and tilt adjustable front seat head restraints
- » Manual front seat head restraint control
- » Driver seat armrest
- » Seek scan
- » Cassette player with auto-reverse
- » 6-disc CD player
- » CD player located in the dashboard/instrument panel
- » Radio data system (RDS)
- » Standard grade speakers
- » 132W amplifier
- » Graphic audio equalizer
- » Audio system theft deterrent
- » Digital signal processor

**Price Disclaimer** - The total sales price is **\$11990.00**. The displayed price is the total sales price not including a **\$495** doc fee, state and local tax, registration fees, interest, or optional products such as GAP insurance or a vehicle service contract. Please see dealer for personalized financing terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Auto Credit Center.

This Page is intentionally left blank



**Below is a list of some major defects that may occur in motor vehicles.**

**Frame & Body**

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

**Engine**

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

**Transmission & Drive Shaft**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

**Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

**Cooling System**

- Leakage including radiator
- Improperly functioning water pump

**Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

**Fuel System**

- Visible leakage

**Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

**Brake System**

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

**Steering System**

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

**Suspension System**

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

**Tires**

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

**Wheels**

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

**Exhaust System**

- Leakage
- Catalytic Converters

**Airbags**

---

*AUTO CREDIT CENTER*

-----  
DEALER

*8201 US HWY 19 PORT RICHEY FLORIDA 34668*

-----  
ADDRESS

*Chris Maher(727-222-5501)*

*Email: Chrisjr@autocreditcenterfl.com*

-----  
SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

-----  
CUSTOMERS SIGNATURE

DATE

-----  
IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)