

# Auto Credit Center

Get Approved Get Driving

## 2019 SUBARU LEGACY

Stock #: 22846

Transmission: CVT

VIN #: 4S3BNAN64K3039625

ENGINE:

INTERIOR: GRAY


DRIVE TRAIN: All-wheel drive

COLOR: GRAY

MILEAGE: 114829



**Tier 4**  
Scan for Pricing and  
Payment Details



**SALES HOURS**  
Mon-Fri 9am-6pm  
Sat- 9am-5pm

**Dealer Contact Info**  
Phone - 727-222-5501  
Info@autocreditcenterfl.com

- » 4WD/AWD
- » ABS Brakes
- » Air Conditioning
- » Alloy Wheels
- » AM/FM Radio
- » Automatic Headlights
- » Cargo Net
- » CD Changer
- » CD Player
- » Child Safety Door Locks
- » Chrome Wheels
- » Daytime Running Lights
- » Deep Tinted Glass
- » Driver Airbag
- » Electrochromic Exterior Rearview Mirror
- » Electrochromic Interior Rearview Mirror
- » Electronic Brake Assistance
- » Fog Lights
- » Front Power Lumbar Support
- » Front Power Memory Seat
- » Front Side Airbag
- » Front Side Airbag with Head Protection
- » Full Size Spare Tire
- » Genuine Wood Trim
- » Heated Exterior Mirror
- » High Intensity Discharge Headlights
- » Keyless Entry
- » Leather Seat
- » Leather Steering Wheel
- » Limited Slip Differential
- » Navigation Aid
- » Passenger Airbag
- » Passenger Multi-Adjustable Power Seat
- » Power Door Locks
- » Power Trunk Lid
- » Power Windows
- » Rear Spoiler
- » Rear Window Defogger
- » Remote Ignition
- » Run Flat Tires
- » Second Row Heated Seat
- » Separate Driver/Front Passenger Climate Controls
- » Sliding Rear Pickup Truck Window
- » Steel Wheels
- » Steering Wheel Mounted Controls
- » Tachometer
- » Telescopic Steering Column
- » Tilt Steering Column
- » Tire Pressure Monitor
- » Traction Control
- » Trip Computer
- » Vehicle Stability Control System
- » Voice Activated Telephone

**Price Disclaimer** - The total sales price is **\$15990.00**. The displayed price is the total sales price not including a **\$495** doc fee, state and local tax, registration fees, interest, or optional products such as GAP insurance or a vehicle service contract. Please see dealer for personalized financing terms.

**Vehicle Details** - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Auto Credit Center.

This Page is intentionally left blank

# BUYERS GUIDE-

IMPORTANT: Spoken Promises are difficult to enforce. Ask the dealer to put all the promises in writing. Keep this form

SUBARU      LEGACY      2019      4S3BNAN64K3039625  
VEHICLE MAKE      MODEL      YEAR      VEHICLE IDENTIFICATION NUMBER(VIN)

## WARRANTIES FOR THIS VEHICLE:

### AS IS- NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE

### DEALER WARRANTY

FULL WARRANTY.

LIMITED WARRANTY. The dealer will pay 100 % of the labor and 100 % of the parts, for the covered system that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions and the dealer's repair obligations. *Implied warranties* under your state's law might give you additional rights.

#### SYSTEMS COVERED:

INTERNALLY LUBRICATED PARTS (ONLY)

ENGINE

TRANSMISSION

DIFFERENTIAL & TRANSFERCASE

DRIVESHAFT & AXLES

#### DURATION:

30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST

30 DAYS OR 3,000 MILES. WHICHEVER COMES FIRST

## NON-DEALER WARRANTIES FOR THIS VEHICLE:

MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired for some components of the vehicle.

MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.

OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty, and an explanation of warranty coverage, exclusions and repair obligations.

SERVICE CONTRACT. A service contract is available at an extra charge on this vehicle. Ask for details as to coverage, deductible, price and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's law may give you additional rights.

#### ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

**OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS.** For information on how to obtain a vehicle history report, visit [ftc.gov/usedcars](http://ftc.gov/usedcars). To check for open safety recalls, visit [safecar.gov](http://safecar.gov). You will need the vehicle identification number (VIN) shown above to make the best use of resources on these sites.

**SEE THE BACK OF THIS FORM for important additional information, including a list of some of the major defects that may occur in used motor vehicles.**

**Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español**

**Below is a list of some major defects that may occur in motor vehicles.**

**Frame & Body**

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

**Engine**

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

**Transmission & Drive Shaft**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

**Differential**

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

**Cooling System**

- Leakage including radiator
- Improperly functioning water pump

**Electrical System**

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

**Fuel System**

- Visible leakage

**Inoperable Accessories**

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

**Brake System**

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

**Steering System**

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

**Suspension System**

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

**Tires**

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

**Wheels**

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

**Exhaust System**

- Leakage
- Catalytic Converters

**Airbags**

---

*AUTO CREDIT CENTER*

-----  
DEALER

*8201 US HWY 19 PORT RICHEY FLORIDA 34668*

-----  
ADDRESS

*Chris Maher(727-222-5501)*

*Email: Chrisjr@autocreditcenterfl.com*

-----  
SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

-----  
CUSTOMERS SIGNATURE

DATE

-----  
IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)