

Auto Credit Center

Get Approved Get Driving

2012 HONDA PILOT

Stock #: 22689R

Transmission: 5-Speed Automatic

VIN #: 5FNYP4H59CB074631

ENGINE: 3.5 L, V6

INTERIOR: Black

DRIVE TRAIN: Four-wheel drive

COLOR: Gray

MILEAGE: 183457



Tier 2
Scan for Pricing and
Payment Details



SALES HOURS
Mon-Fri 9am-6pm
Sat- 9am-5pm

Dealer Contact Info
Phone - 727-222-5501
Info@autocreditcenterfl.com

- » 4WD/AWD
- » ABS Brakes
- » Air Conditioning
- » Alloy Wheels
- » AM/FM Radio
- » Automatic Headlights
- » Cargo Area Cover
- » Cargo Area Tiedowns
- » CD Player
- » Child Safety Door Locks
- » Cruise Control
- » Daytime Running Lights
- » Deep Tinted Glass
- » Driver Airbag
- » Driver Multi-Adjustable Power Seat
- » Electrochromic Interior Rearview Mirror
- » Electronic Brake Assistance
- » Electronic Parking Aid
- » Fog Lights
- » Front Air Dam
- » Front Heated Seat
- » Front Power Lumbar Support
- » Front Side Airbag
- » Heated Exterior Mirror
- » Interval Wipers
- » Keyless Entry
- » Leather Seat
- » Leather Steering Wheel
- » Load Bearing Exterior Rack
- » Manual Sunroof
- » Passenger Airbag
- » Passenger Multi-Adjustable Power Seat
- » Power Adjustable Exterior Mirror
- » Power Door Locks
- » Power Sunroof
- » Power Trunk Lid
- » Power Windows
- » Rear Window Defogger
- » Rear Wiper
- » Running Boards
- » Second Row Folding Seat
- » Second Row Removable Seat
- » Separate Driver/Front Passenger Climate Controls
- » Side Head Curtain Airbag
- » Splash Guards
- » Steering Wheel Mounted Controls
- » Subwoofer
- » Tachometer
- » Telescopic Steering Column
- » Third Row Removable Seat
- » Tilt Steering
- » Tilt Steering Column
- » Tire Pressure Monitor
- » Tow Hitch Receiver
- » Traction Control
- » Trip Computer
- » Vehicle Anti-Theft
- » Vehicle Stability Control System

Price Disclaimer - The total sales price is **\$10990.00**. The displayed price is the total sales price not including a **\$495** doc fee, state and local tax, registration fees, interest, or optional products such as GAP insurance or a vehicle service contract. Please see dealer for personalized financing terms.

Vehicle Details - During our reconditioning process, some listings may display stock photos from the manufacturer. These photos may not match exactly to the actual vehicle for sale. While every reasonable effort is made to ensure the accuracy of this information, we are not responsible for any errors contained on these pages. Please verify any information in person at Auto Credit Center.

This Page is intentionally left blank

Below is a list of some major defects that may occur in motor vehicles.

Frame & Body

- Frame-cracks, corrective welds, or rusted through
- Dog tracks-bent or twisted frame

Engine

- Oil leakage, excluding normal seepage
- Crack block or head
- Belts missing or inoperable
- Knocks or misses related to camshaft lifters and push rods
- Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning of any gear
- Manual clutch slips or chalters

Differential

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible
- Abnormal noise or vibration caused by faulty transmission or drive shaft

Cooling System

- Leakage including radiator
- Improperly functioning water pump

Electrical System

- Batter leakage
- Improperly functioning alternator, generator, battery, or starter

Fuel System

- Visible leakage

Inoperable Accessories

- Gauges or warning devices
- Air conditioner
- Heater & Deforester

Brake System

- Failure warning light broken
- Pedal not firm under pressure (DOT spec.)
- Not enough pedal reserver (DOT spec.)
- Doesnot stop vehicle in a straight line (DOT spec.)
- Hoses damaged
- Drum or rotor too thin (Mfgr. Specs)
- Lining or pad thickness less than 1/32 inch
- Power unit not operating or leaking
- Strucutral or mechanical parts damaged

Steering System

- Too much free play at steering wheel (DOT specs.)
- Free play in linkage more than 1/4 inch
- Steering gear binds or jams
- Front wheels aligned improperly (DOT specs.)
- Power unit belts cracked or slipping
- Power unit fluid level improper

Suspension System

- Ball joint seals damaged
- Structural parts bent or damaged
- Stabilizer bar disconnected
- Spring broken
- Shock absorber mounting loose
- Rubber bushings damaged or missing
- Radius rod damaged or missing
- Shock absorber leaking or functioning improperly

Tires

- Thread depth less than 2/32 inch
- Sizes mismatched
- Visible damage

Wheels

- Visible Cracks, damage or repairs
- Mounting bolts loose or missing

Exhaust System

- Leakage
- Catalytic Converters

Airbags

AUTO CREDIT CENTER

DEALER

8201 US HWY 19 PORT RICHEY FLORIDA 34668

ADDRESS

Chris Maher(727-222-5501)

Email: Chrisjr@autocreditcenterfl.com

SEE FOR COMPLAINTS

I hereby acknowledge notice of the Buyers Guide at the closing of this sale.

CUSTOMERS SIGNATURE

DATE

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removal of this label before consumer purchase (except for the purpose of test-driving) is a violation of federal law (16 C.F.R 455)